

TroubleShooting Kit (CT-T-TK-001)

Ctech Camera Integration Tools

A Division of CCTV Integration Parts

The Troubleshooting Kit (CT-TK-01) provides a method for connecting and troubleshooting distributed Pan/Tilt/Zoom Cameras for quick, convenient installation and Service.

The Kit includes the following items:

- 1 Customized RS232/485-422 Converter w/batteries
- 1 6 Foot RS232/485-422 Custom Test Cable
- 24 Wire Taps for 22-18AWG

Customized RS232/485-422 Converter



6 ft. RS232/485-422 Custom Test cable



24-Wire Taps for 22-18AWG



Quick Connect Installation:

For RS485-422

- * Locate the two data wires closes to the problem dome.
- * Crimp a Wire Tap on each of the two data wires.
- * Insert the two interface connectors into each Tap.
- * Connect the Converter to your Com Port on your Laptop.
- * Install and run CAMTECH LITE or CAMTECH PRO on your Laptop.

For RS232

- * Locate the three data wires closes to the problem dome.
- * Crimp a Wire Tap on each of the three data wires.
- * Insert the three interface connectors into each Tap.
- * Connect the Test Cable to your Com Port on your Laptop.
- * Install and run CAMTECH LITE or CAMTECH PRO on your Laptop.



CAMTech

380 HARGRAVE ST
INGLEWOOD, CA. 90302

CAMTECHTESTER.COM
CAMTECH@PACBELL.NET

Data Sheet # DS-CT-T-TK-001

2/06a